### **Release Note for Vigor2710 Series**

### Firmware Version: 3.6.7 Release Date: July 22, 2014 Applied Models: Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn

• File and Modem Code

(1)For Annex A Model,

- > "v2710\_a\_367" is used for modem code 211011. (Standard)
- ➤ " v2710\_a1\_367" is used for modem code 211801.
- ➤ " v2710\_a2\_367" is used for modem code 2121501.
- ➤ " v2710\_a3\_367" is used for modem code 2211201.
- ≻ " v2710\_a4\_367" is used for modem code 232201. (Recommended for UK SEG)
- > " v2710\_a5\_367" is used for modem code 243601.
- ➤ " v2710\_a6\_367" is used for modem code 243701.
- v2710\_a8\_367" is used for modem code 244001.
- ➤ " v2710\_a7\_367" is used for modem code 2431301.
- > " v2710\_a9\_367" is used for modem code 2471201.

(2)For Annex B Model,

- > "v2710\_b\_367" is used for modem code 2111112. (Standard)
- v2710\_b1\_367" is used for modem code 2111302. (Recommended for Attel Czech only)
- v2710\_b2\_367" is used for modem code 2121302 (recommended for Slovskia only).
- ➤ " v2710\_b4\_367" is used for modem code 214702.
- ➤ " v2710\_b5\_367" is used for modem code 2111312.
- ➤ " v2710\_b6\_367" is used for modem code 215202.
- ➤ " v2710\_b7\_367" is used for modem code 246302.

### **New Features**

• None

# Improvement

- Corrected: CVE-2014-0224 CCS injection vulnerability.
- Corrected: Some DHCP relay issues.
- Corrected: Some SSH memory leakage issues.
- Corrected: DDNS could not work when updating to freedns.afraid.org.
- Corrected: Could not add DHPC option 66/15.
- Corrected: Router dropped all DNS packets with unknown type.
- Corrected: Daylight Saving didn't work with time zone Brasilia (GMT -03:00).
- Corrected: SSH didn't work with Macintosh, while it can work on Windows and Linux.
- Corrected: Some error on External Device Status page.
- Improved: Support Huawei E303D, Vodafone K4201, and SpinCom GPRS Modem.
- Improved: Support NS/ANY/SOA type for DNS cache.
- Improved: IPv6 firewall allows incoming packets transferred to certain ports.
  - If the firmware of the router is upgraded from 3.6.6(or before) to 3.6.7
  - firmware, .all and .rst will have different effects for the incoming packets.
  - 1) .all --> keep routing settings in 3.6.6(or before), (both IPv4 and IPv6)
  - 2) .rst --> block routing packets from WAN in default, (both IPv4 and IPv6)
- Improved: Add some TR-069 parameters for setting WAN >> WAN mode: Backup or Always On, LAN >> DHCP relay enable/disable, DHCP relay IP address and Device hostname, LAN >> Bind IP to MAC, VPN >> Create Phase2 SA for each subnet.(IPSec), VPN >> Netbios Naming Packets Pass/Block, Firewall >> IPv6 Group/IPv6 Object, SNMP, and Diagnostics >> Ping Diagnosis.
- Improved: Support to block Tor tunnel ver. 0.2.3.25, hotspot shield with ver.3.19, telnet protocol by using "putty" or "pietty" for APP Enforcement.
- Improved: Add VLAN tag for WAN IPv6 packets if WAN VLAN tag is enabled.

## **Known Issue**

• None

### Notes

#### Modifications

• None