

Release Note for Vigor2760 Series (Delight)

Firmware Version:	3.8.9.1
Release Type:	Normal
Applied Models:	Vigor2760, Vigor2760n, Vigor2760Vn

DrayTek launches Vigor2760 series – high speed router, perfectly complied with VDSL2/ADSL2/ADSL2+ environment including Vigor2760, Vigor2760n and Vigor2760Vn for speed-wanted customers. For more details of the product information, please visit our website on <http://www.draytek.com>.

File and Modem Code

Note: For DSL models, there will be two folders: STD and VECTOR. The files in VECTOR folder implement a new DSL driver, which supports G.Vectoring on VDSL. If you're using a VDSL line, VECTOR firmware may brings out better performance; however, please consult your ISP to check if G.Vectoring is required. We also provide several versions of Vector firmware to avoid the interoperability issue. You could just try the other one if the one you use cannot synchronize or get the speed that you expected.

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

- "Vigor2760_v3.8.9.1_STD.zip" is used for modem code 548006_544401 & 560816_552011.
- "Vigor2760_v3.8.9.1_VECTOR1.zip" is used for modem code 567517_562301 & 566f07_562701.
- "Vigor2760_v3.8.9.1_VECTOR2.zip" is used for modem code 574307_571801 & 573807_571701.
- "Vigor2760_v3.8.9.1_VECTOR3.zip" is used for modem code 576d17_572801 & 574307_571801.
- "Vigor2760_v3.8.9.1_VECTOR4.zip" is used for modem code 579F17_573F01 & 573807_571701.

For Annex B Model,

- "Vigor2760_v3.8.9.1_STD.zip" is used for modem code 548006_544512 & 551716_553312.
- "Vigor2760_v3.8.9.1_VECTOR1.zip" is used for modem code 565607_567002 & 565606_567002.
- "Vigor2760_v3.8.9.1_VECTOR2.zip" is used for modem code 573307_571c02 &

565607_567002.

- "Vigor2760_v3.8.9.1_VECTOR3.zip" is used for modem code 573307_571c02 & 565607_567002.
- "Vigor2760_v3.8.9.1_VECTOR4.zip" is used for modem code 573307_571c02 & 565607_567002.

New Features

- None.

Improvement

- Corrected: The settings in APP Enforcement Profiles were messed up, after upgrading the firmware to Version 3.8.9.
Suggestion: Choose one of the following methods to upgrade the router firmware.
 - Upgrade the firmware from the old version to new version (V3.8.9.1) directly.
 - Upgrade the firmware to V3.8.9 by using "x.all". Do not modify the APP profile configuration and then upgrade the firmware to 3.8.9.1.
- Corrected: Vigor router reboot randomly due to incompliant with TR-069 server.
- Corrected: Interface for static routes reported on web user interface (GUI) and telnet (CLI) was inconsistent.

Known Issue

- None.