

## Release Note for Vigor2762 Series

Firmware Version:	3.8.9.1
Release Type:	Normal
Applied Models:	Vigor2762, Vigor2762n, Vigor2762ac, Vigor2762Vac

Vigor2762 series, the high speed router, are perfectly complied with VDSL2 environment including Vigor2762n and Vigor2762ac for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2762 series, you can simultaneously engage these bandwidth-intensive applications, such as high-definition video streaming, online gaming, and Internet telephony / access.

### File and Modem Code

**Note:** For DSL models, there will be two folders: STD and MDM. The files in MDM folder named folder include different modem codes. If you're using a VDSL line, MDM firmware may brings out better performance.

Available modem codes for Annex A/Annex B are displayed as follows:

#### For Annex A Model,

- "Vigor2762\_v3.8.9.1\_STD.zip" is used for modem code 776d07\_772801 & 774307\_771801
- "Vigor2762\_v3.8.9.1\_MDM1.zip" is used for modem code 779517\_773F01 & 776d07\_772801.
- "Vigor2762\_v3.8.9.1\_MDM2.zip" is used for modem code 77B506\_775401 & 776d07\_772801.

#### For Annex B Model,

- "Vigor2762\_v3.8.9.1\_STD.zip" is used for modem code 773306\_771502 & 773307\_771C02.
- "Vigor2762\_v3.8.9.1\_MDM1.zip" is used for modem code 773306\_771502 & 773307\_771C02.
- "Vigor2762\_v3.8.9.1\_MDM2.zip" is used for modem code 773306\_771502 & 773307\_771C02.

### New Features

- None.

## Improvement

- Corrected: The settings in APP Enforcement Profiles were messed up, after upgrading the firmware to Version 3.8.9.  
Suggestion: Choose one of the following methods to upgrade the router firmware.
  - Upgrade the firmware from the old version to new version (V3.8.9.1) directly.
  - Upgrade the firmware to V3.8.9 by using “x.all”. Do not modify the APP profile configuration and then upgrade the firmware to 3.8.9.1.
- Corrected: Vigor router reboot randomly due to incompliant with TR-069 server.
- Corrected: Interface for static routes reported on web user interface (GUI) and telnet (CLI) were inconsistent.

## Known Issue

- None.