Release Note for Vigor2762 Series

Firmware Version:	3.8.9.2
Release Type:	Normal
Applied Models:	Vigor2762, Vigor2762n, Vigor2762ac, Vigor2762Vac

Vigor2762 series, the high speed router, are perfectly complied with VDSL2 environment including Vigor2762n and Vigor2762ac for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2762 series, you can simultaneously engage these bandwidth-intensive applications, such as high-definition video streaming, online gaming, and Internet telephony / access.

File and Modem Code

Note: For DSL models, there will be two folders: STD and MDM. The files in MDM folder named folder include different modem codes. If you're using a VDSL line, MDM firmware may brings out better performance.

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

- "Vigor2762_v3.8.9.2_STD.zip" is used for modem code 776d07_772801 & 774307_771801
- "Vigor2762_v3.8.9.2_MDM1.zip" is used for modem code 779517_773F01 & 77B507_775401.
- "Vigor2762_v3.8.9.2_MDM2.zip" is used for modem code 77B506_775401 & 778C06_773F01.

For Annex B Model,

- ➤ "Vigor2762_v3.8.9.2_STD.zip" is used for modem code 773306_771502 & 773307_771C02.
- "Vigor2762_v3.8.9.2_MDM1.zip" is used for modem code 779B06_774F02 & 779B07_774C12.
- "Vigor2762_v3.8.9.2_MDM2.zip" is used for modem code 779906_774402 & 779B06_774C02.

New Features

• Support 4G LTE dongle, QP QLD310 with PPP mode.

Improvement

- Improved: Enhanced the security on the web server.
- Corrected: The information in Dashboard, Bind IP to MAC, and View ARP Cache Table was not displayed periodically.
- Corrected: VDSL connection was unstable.
- Corrected: Firewall did not work on routed LAN.
- Corrected: DSL bandwidth auto detection for QoS didn't work.
- Corrected: LAN configuration change disabled routing mode set previously.
- Corrected: When attempting to apply multiple static routes on the Vigor router through VigorACS, only the first route profile could be created.
- Corrected: Static routes applied by VigorACS (with *.xml) not always held after rebooting CPE.
- Corrected: Unable to access the web user interface by using a particular cloud server.

Known Issue

None.

RD NO: 107_08_29