Release Note for Vigor2925 Series

Firmware Version: 3.7.4_RC3
Release Date: February 11, 2014
Applied Models:
Vigor2925, Vigor2925n, Vigor2925n-plus

Vigor2925 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- Add URL link for dashboard panel.
- Add station list and traffic graph for APM.
- Support CVM (Central VPN Management) function.
- Support VoIP function.
- Support dual 3G/LTE function.
- Support two USB modem status.
- Support IPv6 for SSH.
- Support Rogue AP detection.
- Support AP load balance.
- Support AP Maintenance.

Improvement

- Corrected: Remove WAN budget function.
- Corrected: Acceleration caused TCP drop issue.
- Corrected: Correct iPhone wireless connection droped issue.
- Corrected: No reboot after finishing firmware upgrade.
- Corrected: SSL user can't join user group.
- Corrected: Bind IP to MAC issue on web user interface.
- Corrected: Route priority caused VPN remote dial in user could not access local LAN
- Corrected: Correct VoIP ring issue.
- Corrected: TR-069 error for port status and VoIP status page.
- Corrected: WUI interoperability when IE8 is used.
- Corrected: WAN IP could not be displayed under L2TP mode.

- Improved: Default MTU issue for PPPoE and PPTP setting.
- Improved: SAS voice prompt can not disable.
- Improved: CVM can not display Google map.
- Improved: CVM can not display CPE picture.
- Improved: SIP accounts can not register after change WAN interface.
- Improved: Increase port redirection and open port rule number settings.
- Improved: Enhance WCF function.
- Improved: Add LAN access control.
- Improved: Add TR-069 port in management setting.
- Improved: Increase routed subnet IP pool count from 10 to 32.
- Improved: Modify the web page of Load-Balance/Route Policy by adding the Wizard mode and the Advance mode. In which, the wizard mode allows to configure frequently used settings of route policy via three setting pages. The detailed setting page of Advanced mode is modified by adding some notes.
- Improved: Support longer name for VPN host/server.
- Improved: Wireless wizard modifications.
- Improved: DHCP lease time for subnet.
- Improved: Support a note for Remote Dial-in User authenticating with LDAP server.

Known Issue

- The WAN port can not work well with Alcatel I-040G device. The quick solution is to add another switch between Vigor2925 and Alcatel I-040G.

Notes

Modifications

- None